

TO: ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES & SERVICE CENTERS
ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES REPRESENTATIVES

MODEL AFFECTED: P1412 POWER SUPPLY - REVISIONS C AND D

PROBLEM: HIGH LINE VOLTAGE OR TRANSIENTS CAUSING POWER SUPPLY SCR TO FIRE AND SHUTOFF OUTPUT

## SOLUTION:

Change R8 from 1.3K ½W 5% resistor to 2.2K ½W 10% resistor (Part Number 4704-0222-044)

TECHNICAL SERVICE DEPARTMENT REGENCY COMMUNICATIONS, INC.

